



Service Bulletin

Date: August 1, 2016

Service Bulletin # BSB-002

Page 1 of 1

Subject: Stabalizer Slider Stops

Status: Mandatory

Identification:

All Mayhem BASE parachutes with Nylatron Washer Slider Stops

Background: Bad Seed Base has received reports of the slider getting stuck on the slider stops with Nylatron washers.

Service Bulletin: All Nylatron slider stops to be replaced with 1 ¼" Flat washer by Bad Seed Base, Senior Rigger, Master Rigger or Foreign equivalent. Contact Bad Seed Base for replacement washers .

Compliance Date: IMMEDIATELY, BEFORE NEXT SLIDER UP USE.

Authority: Bad Seed BASE
Brandon Clemons, Owner
709 Yucca St Unit B
Boulder City, NV 89005
Tel: 808-780-2056
Email: info@badseedbase.com